

APPENDIX A

Field Notes

(88) FWDA Facility-Wide April 2015
Groundwater Sampling Event 4/10/15

weather: calm, low 28°F, high 68°F

purpose: complete groundwater sampling,
pull Bennett pumps for maintenance,
clean/organize sampling equipment
and fire station

staff: Ana Cochran, Nadine Warneke, Dave Larsen,
John Nance, Todd Arrowood, Luke Hill

USACE: Andrew Trainor

0705 Arrive at fire station. Conduct daily safety meeting and plan the day's activities. Calibrate sampling equipment and load trucks.

0740 TA and LH depart to sample TMW43
AC and NW depart to sample TMW47

0820 JN and DL buy ice and start pulling Bennett pumps for maintenance.
Pumps pulled from the following wells:
MW24, MW23, TMW19, TMW16, TMW37, +
TMW36

1030-11 TA, LH, AC, and NW Return to fire station to pack samples, unload and clean equipment, clean fire station

12:15 JN and DL return to fire station

1330 All staff depart site back to AIBQ
wells sampled:
TMW43, TMW47

Ana Cochran

4/10/15

(89) FWDA FACILITY-WIDE October 2015
10/26/15 GROUNDWATER SAMPLING EVENT

WEATHER: CALM, LOW 37°F; HIGH 64°F 40% chance of RAIN.

PERSONNEL ON SITE: DAVE LARSEN, LUKE HILL, JENNIE WARNEKE,
GRETCHEN ENGEL, CONNIE WATTAWAHWA-VERNON
RACHEL HOBBS

USACE OVERSIGHT: JUSTIN REALE

0705 - MEET AT COOP'S TRAILER, SIGN IN AND GET SITE SAFETY AND UXO AWARENESS TRAINING

0740 - AT BLDG 34, CONDUCT SAFETY TALK-THROUGH. LUKE/HILL LEADS

0830 - TWO TEAMS SET FOR GROUNDWATER LEVEL COLLECTION:
TEAM 1 - D. LARSEN & C. WATTAWAHWA-VERNON

TEAM 2 - G. ENGEL & R. HOBBS

J. NANCE & L. HILL STAY AT BLDG 34 FOR OFFICE SET-UP AND DELIVERY RECEIVING.

1045 - Portmanteau Towers DROPPED AT BLDG 34

↳ J. NANCE & L. HILL MOVE ICE MACHINE AND REFRIGERATOR TO BUILDING 5. BLDG 34 DOES NOT HAVE Power,

1145 - C.W. VERNON & D. LARSEN RETURN TO BLDG 34

1145 - R. HOBBS & G. ENGEL RETURN TO BLDG 34 -
COLLECTED WATERLEVELS FOR ALL WELLS EXCEPT:
PZ01, PZ02, PZ03, PZ04 PZ05 PZ06 PZ07
PZ08, PZ09, PZ10, FW31

*PROBLEMS ENCOUNTERED: GROUNDWATER WELL KEY SETS
WERE DISASSEMBLED FOR OTHER WORK PRIORITIES,
TOOK TIME TO GATHER NEEDED KEYS - NOTE: ONLY
TWO KEYS TO S1 GATE, AND NO PIEZOMETER KEYS

1700 ALL PERSONNEL OFF SITE, END DAY

John D. Nance

10/26/15

(90)

FACILITY-WIDE OCTOBER 2015
GROUNDWATER SAMPLING EVENT 10/27/2015

WEATHER: CLEAR & COOL, ~30°F

PERSONNELONSITE: DAVE LARSEN, CONNIE WATANAGAHIMA-VERNON, RACHEL HOBBS
BEN MOAYYAD, LUKE HILL, GRETCHEN ENGEL, JOHN NANCE
USACE OVERSIGHT: JUSTIN REECE

0700 TEAM ONSITE, MEET AT FIRESTATION

0730 TAILGATE SAFETY MEETING BY J. NANCE & LUKE HILL

SETUP FOR DAY'S ACTIVITIES -

- GROUNDWATER LEVEL MEASUREMENTS CONTINUED
- COLLECT INITIAL EQUIPMENT BLANK SAMPLE
- BEGIN PURGE OF MONITORING WELLS

TEAMS ARE: C. W. VERNON AND D. LARSEN

J. NANCE AND R. HOBBS

L. HILL AND G. ENGEL WITH B. MOAYYAD

AS FLOATER

0900 ALL TEAMS DEPART FIRESTATION FOR DAY'S ACTIVITIES

0930 CWV & DL AT FW35 - DETERMINED WELL DRY, ONLY
PRODUCED 100ML WATER

1350 RECEIVED DIRECTION FROM USACE TO CUT LOCKS
OFF OF PIROMETERS TO GET WATER LEVELS. CONFIRMED
ENOUGH SPARE LOCKS EXIST AND WILL REPLACE WITH
USACE MONITORING WELL LOCKS

1440 L. HILL & G. ENGEL AT BLDG 5 TO PREP SAMPLE SHIPMENT

1600 J. NANCE & R. HOBBS AT BLDG 5 - CWV & DL TO COLLECT
PIROMETER WATER LEVELS

- PURGED - TMW403, TMW29, MW22S, MW02, MW01
TMW30, TMW31S, TMW31S, TMW46, TMW16,
TMW19, TMW18, TMW37, TMW36
- COLLECTED - FW102015EQU001 EQUIP BLANK (INITIAL)
- GW LEVELS - PZ01, PZ02, PZ03, PZ04, PZ07, PZ08, PZ09,
PZ10

10/27/2015

FACILITY-WIDE OCTOBER
GROUNDWATER SAMPLING EVENT

(91)

~~¶ PROBLEMS ENCOUNTERED: RECEIVED AUTHORIZATION TO CUT
AND REPLACE PZ LOCKS AT 1350, COLLECTED ALL
PZ GW LEVELS EXCEPT PZ05 & PZ06. IN CUTTING
THE LOCKS, PZ02 AND PZ09 WELL COVERS WERE BROKEN.
LIDS STILL SEAT ONTOP OF WELL CASING, HOWEVER ARE
NOT ABLE TO BE LOCKED.~~

1730 ALL PERSONNEL OFF SITE, END DAY

10/27/15

John Nance

(92)

(redacted) 10/28/2015

GROUNDWATER SAMPLING EVENT 10/28/15

WEATHER: OVERCAST
CLEAR AND COOL, ~30°F LIGHT BREEZE AM

PERSONNEL

ONSITE: JHN NANCE, RACHEL HOBBS, LUKE HILL, DAVE LARSEN

CENNIE VATHAWACHINDA-VERNON, BRETT HANINGER

VSACE OVERSIGHT: JUSTIN PENNE

0700 - ONSITE AT FIRSTATION, BEGIN SAFETY TAILGATE
BY J. NANCE AND L. Hill

0715 - CALIBRATE EQUIPMENT, PREP FOR DAY'S ACTIVITIES:

- COLLECT REMAINING PERMETER GW LEVELS
- CONTINUE PURGING OF MONITORING WELLS
- BEGIN SAMPLE COLLECTION FROM PURGED WELLS

TEAMS ARE: JN, RH, CWV, DL, LH, GE

0750 DL, CWV DEPART TO COLLECT PZ WATER LEVELS

0800 COLLECT PZ06 DTW MEASUREMENT

0809 COLLECT PZ05 DTW MEASUREMENT

0845 LH, GE DEPART TO PURGE WELLS

1000 JN, RH DEPART TO COLLECT SAMPLES

1415 ALL TEAMS AT BLDG 5 TO PREP SAMPLES TO SHIP

- PURGED: TMW41, TMW44, TMW21, TMW22,
- SAMPLED: TMW14, TMW19, TMW37, TMW36, MW22S,
TMW29, TMW40S, MW02, MW01
- COLLECTED GW LEVELS PZ05, PZ06

† PROBLEMS ENCOUNTERED: HORIBA WATER METER HAD PROBLEMS

CALIBRATING, NEEDED TO USE BACKUP METER. HACH

TURBIDITY METERS NOT CALIBRATING, TEAMS USED

NTU READINGS FROM HORIBA METERS. PZ05 AND

PZ06 DTW MEASUREMENTS COLLECTED ON THIRD DAY,

HOWEVER, DTW MEASUREMENTS ON MONDAY BEGAN AFTER 0830

AND PZ05/PZ06 WAS COLLECTED BEFORE 0830 ON WED. THIS

TECHNICALLY ACHIEVES THE 48 HOUR WINDOW PER THE WORK PLAN.

10/28/15

FWDA FACILITY-WIDE OCTOBER 2015
GROUNDWATER SAMPLING EVENT

(93)

CONTINUED -

1630 ALL TEAMS OFF SITE, SAMPLES SHIPPED
END OF DAY

10/28/15

John D. Penne

(4)

(2nd day of 1) & 2015

GROUNDWATER SAMPLING EVENT 10/29/15

WEATHER: PARTLY CLOUDY, CALM ~38°F AM
CLOUDY AND RAIN ~40°F PM

PERSONNEL: DAVE LARSEN, JOHN NANCE, RACHEL HOBBS, LUKE HILL
ONSITE CONNIE WATTANACHINDA - VERNON, GRETCHEN ENGEL

USACE OVERSIGHT: JUSTIN REALE

0700 TEAMS ONSITE AT FIRESTATION

0715 SAFETY TAILGATE BY J. NANCE & L. HILL

0730 CALIBRATE EQUIPMENT, PREP FOR DAY'S ACTIVITIES

- CONTINUE PURGING MONITORING WELLS
- COLLECT GROUNDWATER SAMPLES

TEAMS ARE: JN, RH; DL, CWV; LH, GE

0830 ALL TEAMS DEPART FIRESTATION

1040 LIGHT RAIN AND OVERCAST

1345 ALL TEAMS AT BLDG 5 TO PROCESS AND
PACK SAMPLES TO SHIP

- PURGED: BGMW03, TMW33, TMW23,
- SAMPLED: TMW46, MW22S, MW02, MW01, TMW47
TMW22, TMW21, TMW44, TMW39, TMW31S
TMW30, TMW18

* PROBLEMS ENCOUNTERED: FIELD PRINTER NOT WORKING, HAND
WRITING FINAL CHAIN OF CUSTODY'S FOR SAMPLE
SHIPMENT

1700 ALL TEAMS OFF SITE, SAMPLES SHIPPED
END DAY

John David 10/29/15
Nance

(5)

FWDA FACILITY-WIDE OCTOBER 2015

10/30/15 GROUNDWATER SAMPLING EVENT

WEATHER: OVERCAST AND RAIN 35°F

PERSONNEL: DAVE LARSEN, JOHN NANCE, LUKE HILL, RACHEL HOBBS
ONSITE CONNIE WATTANACHINDA - VERNON, GRETCHEN ENGEL

USACE

OVERSIGHT: JUSTIN REALE

0700 ONSITE AT FIRESTATION

0715 SAFETY TAILGATE BY J. NANCE AND L. HILL

0730 CALIBRATE SAMPLING EQUIPMENT AND PREP FOR DAY'S
ACTIVITIES

- CONTINUE PURGING MONITORING WELLS
- CONTINUE COLLECTING GROUNDWATER SAMPLES

TEAMS ARE: JN, RH; DL, CWV; LH, GE

0815 ALL TEAMS IN FIELD FOR DAY'S ACTIVITIES

1120 RAIN STOPPED, HUMID AND COLD WITH LIGHT WIND

1330 ALL TEAMS RETURN TO BLDG 5 TO PROCESS AND
PREP SAMPLES FOR SHIPMENT

- PURGED: TMW07, FW31, MW18D

- SAMPLED: TMW07, MW22S, TMW40S, TMW22
TMW23, TMW33, BGMW03, MW03, TMW26
TMW27,

* PROBLEMS ENCOUNTERED: NO INCIDENTS OR PROBLEMS TODAY

1530 SAMPLES SHIPPED

1600 ALL TEAMS OFF SITE FOR WEEKEND

John David 10/30/15
Nance

(96)

FWDA FACILITY-WIDE OCTOBER 2015

GROUNDWATER SAMPLING EVENT

11/2/2015

WEATHER: CLEAR AND COLD, ~ 25°F

PERSONNEL: JOHN NANCE, RACHEL HOBBS, LUKE HILL, DAVE LARSEN

ONSITE: CONNIE WATANAKHINDA-VERNON, SHANNON WEGESSER

USAC

OVERSIGHT: JUSTIN REALE

0700 PERSONNEL ONSITE AT THE FIRESTATION

0710 TAILGATE SAFETY MEETING BY J. NANCE & L. HILL

0720 CALIBRATE SAMPLING EQUIPMENT, LOAD SUPPLIES
FOR DAY'S ACTIVITIES

• COLLECT GROUNDWATER SAMPLES

0830 ALL TEAMS IN FIELD TO COLLECT SAMPLES

0930 JN, RH CONTROL BOX FOR LOW-FLOW PURGING IS NOT
WORKING — RADIO J. REALE TO BE ON WATCH FOR FEDEX
DELIVERY OF BACK-UP CONTROL BOX

0945 FED EX DELIVERS CONTROL BOX


1420 ALL TEAMS AT BLDG 5 TO PROCESS AND
SHIP SAMPLES

JDN
 COLLECTED SAMPLES: MW22S, MW22D, MW20, FW31
 FW31 EQUIP BLANK, MW18D

★ PROBLEMS ENCOUNTERED: REQUIRED CONTROL BOXES NOT
FUNCTIONING PROPERLY, NEEDED TO USE RENTED BOX

1530 SAMPLES TAKEN TO FEDEX TO SHIP

1600 OFF SITE, END DAY


 11/2/15

11/3/2015

FWDA FACILITY-WIDE OCTOBER 2015

GROUNDWATER SAMPLING EVENT

(97)

WEATHER: BREEZY AND COOL, CLEAR ~ 38°F AM

CLEAR AND BREEZY, ~ 55°F PM

PERSONNEL: JOHN NANCE, RACHEL HOBBS, DAVE LARSEN, LUKE HILL,

ONSITE: SHANNON WEGESSER, CONNIE WATANAKHINDA-VERNON

USAC

OVERSIGHT: JUSTIN REALE

0710 ONSITE AT FIRESTATION

0720 SAFETY TAILGATE BY J. NANCE & L. HILL

0730 CALIBRATE EQUIPMENT AND LOAD SUPPLIES FOR DAY'S
ACTIVITIES

• COLLECT GROUNDWATER SAMPLES

0800 ALL TEAMS IN FIELD TO COLLECT SAMPLES

LH, SW GO TO HOME DEPOT TO REPLACE FAULTY
POWER INVERTER

0830 LH, SW BACK ON SITE


1430 ALL TEAMS AT BLDG 5, PREP AND PROCESS SAMPLES
TO BE SHIPPEDSAMPLES: MW22S, TMW17, TMW40D, TMW14A,
TMW43, TMW45, SMW01, TMW34, TMW2,

NO PROBLEMS ENCOUNTERED TODAY

1530 SAMPLES TAKEN TO FEDEX

1620 COLLECT TMW28 (DOES NOT HAVE NITRATE) AND STAGE
TO BE SHIPPED ON 11/4/15

1715 ALL PERSONNEL OFF SITE, END DAY


 11/3/15

(98)

FWDA FACILITY-WIDE October 2015
GROUNDWATER SAMPLING EVENT 11/4/15

WEATHER: SNOWY/SLEET MIX, ~30°F WINDY AM
SNOW SLEET INTERMITTENT FLURRIES, ~25°F WINDY PM
PERSONNEL JOHN NANCE, BEN MARYYAD, LUKE HILL, DAVID LARSEN, MICHELLE HOBBIS
ONSITE, SHANNON WEGESSER, CONNIE WATANAGHINDA-VERNON
USACE
OVERSIGHT: JUSTIN REALE

0700 ONSITE AT FIRESTATION

0710 TAILGATE SAFETY BY L.HILL & B.MARYYAD

0725 CALIBRATE SAMPLING EQUIPMENT, LOAD FOR
DAY'S ACTIVITIES

- COLLECT GROUNDWATER SAMPLES

FIELD TEAMS ARE: LH, SW, CWV, DL, RH, BM

0750 ALL TEAMS DEPART FIRESTATION FOR DAY'S ACTIVITIES

1430 ALL TEAMS AT BLDG 5 TO PROCESS SAMPLES FOR
SHIPMENT

- SAMPLED: MW22S, TMW06, TMW04, TMW48,
TMW45, TMW31D, TMW08, TMW03, TMW39D,
TMW11

* No problems encountered today, did have
some issues with control box but was able
to fix

1530 SAMPLES TAKEN TO FEDEX TO SHIP

1645 ALL PERSONNEL OFFSITE, END DAY

11/4/15

(99)

FWDA FACILITY-WIDE October 2015
GROUNDWATER SAMPLING EVENT

WEATHER: SNOWY AND BREEZY, ~20°F COLD AM
PARTLY CLOUDY AND COLD ~35°F PM

PERSONNEL JOHN NANCE, LUKE HILL, SHANNON WEGESSER, DAVID LARSEN
ONSITE: MICHELLE HOBBIS, CONNIE WATANAGHINDA-VERNON

USACE

OVERSIGHT: JUSTIN REALE

~~John Nance~~

0710 ARRIVE ONSITE AT FIRESTATION

0735 SAFETY TAILGATE BY J.NANCE

0745 CALIBRATE SAMPLING EQUIPMENT, LOAD SUPPLIES
FOR DAY'S ACTIVITIES

- COLLECT GROUNDWATER SAMPLES
- PURGE AND SAMPLE MW23 & MW24

0815 ALL TEAMS IN FIELD FOR DAY

0900 CLOUDS PART, SUN IS OUT. MELTING FROZEN GROUND
AND MAKING DIRT ROADS DIFFICULT TO PASS1510 ALL TEAMS AT BUILDING 5, PROCESS SAMPLES
FOR SHIPMENT

- SAMPLED MW24, TMW45, TMW31D, TMW08
BGMW01, BGMW02, TMW11, TMW47
- PURGED MW23

* No problems encountered today

1540 SAMPLES TAKEN TO FEDEX TO SHIP

1700 ALL PERSONNEL OFF SITE, END DAY

11/5/15

(165)

FNDA FACILITY-WIDE OCTOBER 2015
GROUNDWATER SAMPLING EVENT 11/6/15

WEATHER: MOSTLY CLOUDY, CALM AND COLD ~ 21°F AM

PERSONNEL JOHN NANCE, DAVE LARSEN, RACHEL HOBBS, LUKE HILL
ONSITE: SHANNON WEGESSER, CONNIE WHITMAN/HINDA-VERNON

USACE

ONSITE: JACKIE SMITH

- 0625 JN, RH ONSITE TO ACCESS MW23 BEFORE GROUND THAWs
- 0700 ARRIVE REMAINING CREW ARRIVES ONSITE.
- 0735 SAFETY TAILGATE BY L.HILL
- 0740 CALIBRATE EQUIPMENT, PREP FOR FINAL DMWS SAMPLING
 - COLLECT GROUNDWATER SAMPLES.
 - CLEAN WORK AREAS
 - DEMOB FROM SITE
- 0845 TUBING SPLIT AT TMW24 - NEEDS REPAIR
- 0945 RH, JN RETURN FROM DMW23, DROP SAMPLES AT BLDG 5
- 1015 JN AT TMW24, REPAIR AIR & WATER LINES
CWV & DL TO SAMPLE TMW24
- 1300 ALL TEAMS AT BLDG 5. PREP SAMPLES FOR SHIPMENT AND CLEAN WORK AREAS
- 1430 SAMPLES TAKEN TO FED EX
- 1500 CHECK IN RADIOS, KEY SETS. VERIFY CLEANUP WITH USACE. DEMOB FROM SITE, END FIELD EVENT
 - SAMPLE TMW38, MW23, TMW24, TMW15
 - * NO PROBLEMS ENCOUNTERED TODAY

END DAY

John Nance 11/6/15

92 Location FWDA Date 4/10/2015
 Project / Client Facility-Wide April 2015
 Groundwater Sampling Event

- 1110 Return to fire station to pack samples and unload equipment. Clean fire station, conduct equipment inventory, breakdown recycle materials.
 1225 Depart to FedEX
 1330 Return to fire station to load luggage / return FWDA Keys. Depart site - return to ABQ.

Aqua Cetraur

4/10/15

Location FWDA Date 4/10/2015
 Project / Client Facility Wide Groundwater Sampling Event October 2015

- 0700 Meet on site - check in with USACE; Safety briefing
 0845 Mob to building 43, assemble equipment for day. Clear, 40 F
 0930 leave building 43 to begin water levels
 Personnel on site J. Nance, Luke Hill, Connie Vernon, Dave Gretchen Engel, Rachel Hobbs G. Engel & R. Hobbs on book
 0935 Arrive at TMW-41, 0950 TMW22, 1002 TMW4A, 1010 TMW03
 Ant hills at TMW03 → strategize how to set up for sampling, anthill at TMW03b, ~~AT~~
 1023 TMW01, 1030 TMW36-cob webs in well vault, 1043 TMW02, 1047 TMW40S, 1050 TMW40D, 1100 TMW47, 1119 395, ¹²⁰³ 39P, ¹²⁰⁰ 39L, TMW31S, 1205 TMW31D, 1210 TMW48, 1222 TMW37, ¹²⁰² 1234 TMW01, 1235 Weather over cast, breezy, 1305 TMW30, 1310 TMW49, 1322 TMW45, 1330 TMW15, 1337, TMW17, 1357, TMW14a

94

Location FWDA

Date 10/26/15

Project / Client Facility Wide Groundwater
Sampling Event October 2015

- 1406 TMW 16 1419 TMW 18
 1430 Meet at Nance and Luke Hill,
 to see how to get to TMW 19
 1456 TMW 19,
 1508 TMW 29
 1517 TMW 38
 1528 TMW 31, 1536 TMW 32, 155 TMW 43
 1603 TMW 21
 1615 Return to Building 43, turn in
 paperwork. End of day

Rachel Mable

10/26/15

Location FWDA

Date 10/27/15-95

Project / Client Facility Wide Groundwater
Sampling Event October 2015

- 0700 Team on site Luke Hill, Ben
 Moayyad, Gretchen Engel, John Nance,
 Connie Vernon, Rachel Hobbs, David Larsson
 Weather clear cool 30°F
 Health and safety briefing Planning
 day & week. Load vehicles and calibrate
 equipment.
 Leave for sampling. Perform equipment
 blank on Grundfos pump
 Team: Luke on back Luke Hill
 Ben Moayyad, Gretchen Engel
 0900 Collect FWDA 2015 EQ001
 [TB-01 - 102015]
 0940 Collect FWDA 2015 EQ001
 1015 Headed to TMW-30 to
 purge
 1045 Begin purging TMW-30
 1052 TMW-30 purged dry
 1120 Begin purging TMW-315
 1133 TMW-315 purged dry
 1144 Dumping purge water
 1205 Begin Purging TMW-395
 1214 TMW-395 purged dry
 1245 Begin Purging TMW-46
 1256 TMW-46 purged dry

96

Location FWDA Date 10/27/15
 Project / Client Facility Wide Groundwater
 Sampling Event October 2015

- 1310 Drop off equipment @ fire station.
- 1325 Dump Purge Water @ evaporation basin
- 1340 Packing equipment blank sample for shipment
- 1440 Headed to FedEx to ship samples
- 1515 Samples shipped
- 1525 Picking up nitrogen tanks
- 1615 Nitrogen tanks delivered to site
- 1630 Leaving site —

JM 10/27/15

97

Location FWDA Date 10/28/15
 Project / Client Facility Wide Groundwater
 Sampling Event October 2015

- 0700 Onsite. Health & safety briefing
 Equipment calibration. Planning for day. John Vance, Rachel Hobbs, Dave Larson, Connie Vernon, Luke Hill, Gretchen Engel Book - Luke Hill & Gretchen Engel
- 0850 To TMW 21
 Clear, calm, overcast 40°F
- 0952 Purged TMW41 at with Grundfos pump
- 0959 End purge
- 1056 TMW 44 purged with Grundfos
- 1100 End purge
- 1219 TMW 21 Purged with Grundfos
- 1227 End purge Missing well cap
- 1321 TWW 22 purged with Grundfos
- 1325 End purge
- 1400 Onsite to pack samples
- 1600 At Bldg 34 to unload
- 1545

1630 Offsite

YdS

10.28.15

98

Location FFWA

Date 10.29.15

Groundwater

Project / Client Facility - Wide October 2015
Sampling Event October 2015

0700 Team onsite

Luke Hill, Gretchen Engel, John Vance,
 Dave Larson, Rachel Hobbs, Connie Vernon
 Safety Meeting - Slips, trips, falls, pinch
 points Weather cool and clear 35°F

Book → Luke Hill and Gretchen Engel

Loaded trucks, calibrated equipment

0850 Onsite at BGMW03

0900 Purge

0916 End purge

1020 Onsite TMW33

1041 End purge

1120 Onsite TMW23

1143 End purge

1240 Onsite TMW46

Sample collected 1300

1320 Back to Bldg 5 to pack
samples

1400 At Bldg 31 to unload truck

1700 Offsite

10.29.15

Location FFWA

Date 10.30.15

99

Project / Client Facility - Wide Groundwater
Sampling Event October 2015

0700 Team onsite

Luke Hill, Gretchen Engel, John Nance,
 Dave Larson, Rachel Hobbs, Connie Vernon
 Safety Meeting - Slips and trips, rain -
 slick truck beds.

Calibrated Horiba i turbidity meter
 Loaded trucks

This book → Luke Hill & Gretchen Engel

Weather 35°F raining

0815 Onsite TMW07

0828 End purge

0930 Onsite FW31

0947 End purge

Rain stopped approximately 0900

1100 Onsite MW18D Temp. 40°F

1121 End purge

1200 Onsite TMW07 to sample

1210 Sample time

Collected full suite

1300 Returned to ship samples

1530 Samples sent to FedEx

Unload truck

Offsite to Albuquerque

2015/10/30/15

100

Location FWDA Date 11/2/15
 Project / Client Facility - Wide Groundwater Sampling Event - October 2015

- 0700 Arrive @ fire station
 0710 H+S Meeting. Review of week's activities
 0720 Loading equipment into trucks
 0725 Personnel: L.Hill + S.Wegesser
 0800 Collecting bottle sets for today's sampling; Pick up bailers @ hotel
 [0930] Collect FWB1102015EBUD02
 1030 Head to FW-31
 [1105] Collect FWJ31102015
 1145 Heading to MW-18D
 [1230] Collect MW18D102015
 1300 Packing Samples
 1400 Shipping Samples
 1630 Unloading Equipment @ Fire Station
 1700 Leaving site —

11/2/15

Location FWDA



Date 11/3/15

101

Project / Client FACILITY-WIDE GROUNDWATER SAMPLING EVENT - NOVEMBER/OCTOBER 2015

- 0715 ARRIVED @ FIRE STATION
 0720 H+S MEETING, REVIEW OF DAY AND WEEKS ACTIVITIES
 0730 DROVE INTO TOWN TO PURCHASE POWER CONVERTER
 0800 RETURNED TO SITE, COLLECTED BOTTLE SETS FOR DAY'S SAMPLING EVENT
 0830 HEADED TO TMW43102015 TO COLLECT SAMPLES
 PERSONNEL: L.HILL + S.WEGESSER,
 WEATHER CLEAR, ~50° F
 0905 Setting up @ TMW43
 [0950] Collect TMW43102015
 DTW43102015
 TMW43102015MS
 TMW43102015MSD
 1300 Setting up @ TMW45
 [1250] Collect TMW45102015
 1335 Begin Packing samples
 1535 Samples shipped; Begin preparation for tomorrow's sampling
 1645 Leaving site —

11/3/15



104 Location FNDA Date 11/16/2015
 Project / Client FACILITY-WIDE TREATMENTWATER
SAMPLING EVENT

0730: ARRIVED ON SITE
 PERSONNEL: LUKE HILL, SHANNON NEGESSER
 0735: LOADING EQUIPMENT INTO TRUCKS
 WEATHER: CLEAR, SUNNY, 20°F, WIND CALM
 0745: H+S MEETING + REVIEW OF DAILY
 + WEEKLY ACTIVITIES
 0830 Setting up @ TMW-24
 0845 Nitrogen tubing spl.t. Heading
 to TMW-38. Will repair TMW-24
 following TMW-38 sampling.
 1000 Collect TMW 38 10/2015
 1135 Return to Building #5 to
 pack samples
 1200 Packing samples, Unloading
 equipment, cleaning up
 1400 Shipping samples
 1430 Clean up
 1500 Leaving site

11/16/15


105 Location _____ Date _____
 Project / Client _____

10/26/15 Fort windgate Ground Water
Staff: David Larsen and Constance ^{Sampling}
Wattanachinda Vernon
9:30am Arrived at MW 23.

10:00am Arrived at PZ 10 wells. Took out bucket and equipment. We found that we did not have the keys to these wells. Dave called John to inform him that we don't have the well keys. John said Do the wells we have the keys for and return later to complete the PZ 10 wells after we get the keys.

10:30 We went to see John and Luke in person. Dave talk to John again about the PZ 10 Keys. John said he will check for us. John told us to continue with the wells on our list that we have keys for.

10:50 Dave accidentally dropped the rubber top to well Blm MW 2 inside of the well casings.

12:30-12:50 we ate lunch.

2:15 we were approved for access to wells to TMW 27 and SMW 01. John gave us a code to use ~~the~~ one of the locks and the lock still did not open. We were able to open ~~one~~ of the locks with a key. We returned to the fire station after we completed all assigned wells except for the "PZ's". As of 3:20pm we do not have keys / access to these wells. John is currently working on getting us the keys. All of the work has been smooth without any incidents.

16:20 Leaving the site

10/26/15

R. Wat Vae

10/27/15 Fort windgate Depot Vernon
Staff: David Larsen and Constance Wattanachinda
Started work at 8:00am

Arrived at 9:30am - FW 35 we were only able to bail 100 ml. The well seems like it may be dry ing.

09:52 Arrived at TMW 40S.
10:02 Arrived at TMW 4. Turbidity meter broke. After the 3rd reading. We were unable read the NTC for the 4th reading. Dave called John and told him about the problem with the meter. Dave and I returned back to the fire Station to fix the meter if possible. Dave also changed the batteries. The meter was unable to be repaired for use. Dave called John and let him know we are going use the NTU readings from the Horiba for the rest of the day.

11:15am Arrived at TMW 29. Due to the loss of the Turbidity Meter, we are using the Horiba meter to check the NTU readings.

12:39pm Arrived at MW 22S. We took one reading from the well because, we only were able to collect 700 ml.

Arrived at MW 22S at 12:49pm we were able to collect only 700 ml.


1:03pm Arrived at MW 02, we were able to take 3 readings. We used the Horiba meter for the "NTU" reading.

1:56pm We arrived at MW 01 - we were able to take 3 readings. This well had plenty of water. Dave and John were working on getting keys or replacing the locks on the "PZ" wells.

John informed Dave - we had approve to remove the old locks from the "PZ" wells and replace with new locks. Dave and myself found a lock cutter and we replaced the locks on the following

Wells. "PZ" 1, 2, 3, 4, 7, 8, 9, and 10.
 Dave and myself with continue on 10/28/15
 early morning to complete the readings
 for "PZ" wells 5 and 6. While cutting the
 cocks for replacement on "PZ" wells 2 and 9.
 Dave accidentally broke the well covers.
 John and Dave will be working on
 replacement covers on 10/27/15.
 Today was a great day and we were
 to completed all assigned work
 without incidents. PZ well cock replacement
 4:20pm — 5:30pm

10/26/15



10/28/15 FWDA - Ground Water Sampling Oct 2015
 Staff David Larsen and Constance Wattanachinda-
 Vernon

7:05am 7:50am Safety meeting w/ John
 and Luke and Staff,
 7:51am Dave and myself drove out to ~~have~~
 the DWT's on PZ 5 and PZ 6.
 8:00am arrived at PZ 6 walked to location from road.
 8:09 arrived at PZ 5 walked to location from PZ 6.
 8:20am went back to fire station to pick up Sampling
 Supplies and equipment for the day.
 8:50am Arrived at ~~TMW~~ MW225 for sampling
 0945am Arrived at TMW29 for Sampling
 10:30am Arrived at TMW405 for Sampling
 11:25am arrived at MW02 for Sampling
 12:30pm arrived at MW01 for Sampling
 Returned to fire Station at and then to
 Blvd 51 to prepare Samples for shipping.
 1:20pm We are at Blvd 51 working on
 the coolers and preparing for shipping.
 We packed coolers, samples and ice to
 ship the samples.
 3:25pm Dave and myself were assigned
 to take the samples to fedex. We delivered
 all samples to the fedex store by 3:54pm.
 All samples in ice chest will be on the fedex
 truck today.

10-28-15



10/29/15 FWDA Groundwater Sampling
Staff David Larson and Constance
Wattanathinda Vongs

0400 Safety meeting with John.

0750 Started collecting our supplies
for the day.

0821 We arrived at TMW405 to
collect samples. The weather is cold and
slightly rainy.

0911 Arrived at MW22S for Sampling

0950 Arrived at MW02 for Sampling

1010 Arrived at MW01 for Sampling

1042 Arrived at TMW41 for Sampling

We started getting a little rain.

1159 Arrived at TMW22 for Sampling.

Lightly raining and cold outside.

1305 Arrived at TMW21 for Sampling.

it is raining a little more. We are still
able to proceed with our sampling task.

1340 We returned to the fire station because

we completed all of our samples for the

day. Dave and myself emptied out the

back of our truck. Because we're going to

deliver the samples to FedEx after the

samples ice chest were ready for shipping.

All team members worked together to

prepare the ice chest and samples for

shipping.

1640 Dave and myself drove to the FedEx

location to drop-off the ice chest filled

with samples.

1855 all samples delivered to FedEx

and placed on the truck. Dave and myself

waited at FedEx until all ice chest were

placed on the truck. Today was a great day

1700 Dave and myself are off from work.

10/29/15
Dave
Wattanathinda
Vongs

10/30/15 FWDA Groundwater Sampling
Staff David Larsen and Constance 10/2015
Wattanachinda-Vernon

0700 Staff meeting

0750 Started packing the truck ^(P) with Supplies and equipment for Well Sampling.

0802 Arrived at MW22S for Sampling. This well is very close the Blvd we get our supplies from. Today started out very cold and rainy.

0855 Arrived at TMW40S. It is raining and cold. We were able to do our sampling without any problems.

0920 Arrived at TMW22. It is raining, cold and slightly windy. We are able to sample.

0943 Arrived at TMW23 for Sampling.

1120 Arrived at TMW33 for Sampling. The rain has stopped. We were able to collect the samples without getting too wet. Hopefully the rain has stopped for the day. Took 15 samples.

12:30pm arrived at BGMW03 this is the last well for us today. We will report to Building 51 to prepare the samples for shipping.

1:30pm Dave and Myself returned to the fire station to put our supplies and equipment in storage and clean our truck bed out. We will be delivering the samples inside of the ice chest to the FedEx office.

3:30pm Dave and Myself drove the samples to the FedEx office. We waited at the FedEx store to ensure that all ice chest with samples were placed on the truck.

Today was cold, and wet! The whole team had a great day without incidents!

~~Completed 10-30-15~~

10/2/2015 FWDA Groundwater Sampling
Staff David Larsen and Constance 10/2015
Wattanachinda-Vernon

0700 staff meeting

0800 Started collecting Supplies and Equipment for today.

0900 TMW35 - setting up equipment for well testing / samples -

0955 Started collecting Samples. The process was completed at 11:00.

11:15 Arrived at MW22S to collect additional samples. We had to do a partial again today because the well only had 500 mL. And the well went dry.

11:25 We cleaned the equipment to prepare to collect samples from well 22D.

22S and 22D are at the same location.

11:35 We started collecting samples from 22D. The process took awhile because we had to collect several readings before we could collect the samples.

12:10pm We started collect the water for the samples.

1:45pm we finished collecting samples for 22D.

We are cleaning equipment and going to Blvd 51 to start checking our sample list and prepare the samples for shipping.

2:20pm We empty our truck return our equipment to the fire station.

3:20pm We leave Fort Windgate to take the samples to FedEx.

4:00pm We return the generator to the rental company. See Book 11/2/15

11/3/15 FWDA Groundwater Sampling
 Staff Dave Larsen and Constance Wattanaphinda 102015
 0700 arrived at the fire station.
 0710 Safety meeting with John and crews. 0730 starting loading up the truck with equipment and supplies.
 Arrived at MW22 S 0741 to take samples we were only able to obtain 1 sample.
 0946 Arrived at TMW17 to collect samples we set up the equipment to purge the well, took data into every 3 minutes and collected samples at 10:18 am.

Before we arrived at TMW17 we arrived at TMW40B at 8:26 am. We purged this well and collected samples at 9:00 am.

11:24 am we arrived at TMW14A to purge and collect samples. We collected the samples at 12:00 pm. We arrived at the fire station at 1:45 pm to return all of our equipment to our space. All wells were able to collect the purged samples. 2:15 pm we arrived at Building 51 to prepare samples for shipping.

3:30 pm all samples ready to ship. Dave and myself are going to deliver all samples to FedEx. Today was a great day. All team members worked together and did an awesome job!

Constance Wattanaphinda 11/3/15

11/4/15 FWDA Groundwater Sampling 102015
 Staff Dave Larsen and Constance Wattanaphinda
 0700 arrived at fire station - Vernon
 0710 Safety meeting with John and crew members.
 0740 Started loading up the truck with supplies and equipment. Stopped by Blvd 51 to pick up additional supplies.
 0800 arrived at MW22 S to take the last sample, 0810 we were able get enough water to collect the last sample. We left the well to go to TMW06. We arrived at 0839.
 0839 Arrived at TMW06 we set up and started the purging process. We collected samples at 0904 and finished at 1020.
 1035 we arrived at TMW04 to purge the well, and collect samples. We started collecting samples at 11:04 until 1225.
 12:35 we arrived TMW40 we started the purge process and collected samples 13:04 until 13:47. The weather all day has been cold, wet, snowy and rainy.
 14:00 we returned to Blvd 51 and then we went the fire station to unload the truck and prepare to deliver the samples to FedEx. We return to Blvd 51 to prepare the samples for shipping. All crew members worked to prepare samples for shipping. Today was a great day!

Dave Larsen 11/4/15

11/5/15 FWDA Groundwater Sampling
0700 arrived at the fire station. There is snow everywhere, due to a severe snow storm last night. All team members dressed warm and prepared for the cold temperatures.
0710 Safety meeting with John. All team members present. John discussed safety in extreme cold weather and other safety issues.
0800 we started loading our truck with supplies and equipment for the day. And then we drove to Blvd 5 to pick up additional sampling supplies.
0834 arrived at B&G MW01 started the purge process at 0845. Took Samples at 0900 until 1018. Drove to B&G MW02.
Arrived at B&G MW02 at 1023. Started purging the well at 1031. Started taking samples at 1050. finished at 1150.
1200 arrived at Blvd 5 to Pick up more 1 liter amber bottles.
1220 arrived at TMW11 to complete the Partial Sample collection on 11/4/15. Started Sample collection at 1240. finished at 1305.
1318 we arrived at TMW47. Started the purge process at 1325. Took Samples at 1340 and finished at 1447.
1505 we arrived at Blvd 5 to prepare all the samples for shipping for each Team. Dave and myself delivered all ice chest with samples to fedex. Today was very cold, wet and cloudy. All team members did a great job!

11/5/15
C. O. Waller

11/6/15 FWDA Groundwater Sampling
Staff Dave Larsen and Constance Wattanachinda Vernon 0700 arrived at the fire station. There is still a little snow and ice on the ground. Safety meeting with Luke. Watch out for ice, be careful driving in the mud. Try not to get stuck, watch where you are walking. We started loading up our truck with supplies and equipment for the day. We went to building 5 for additional supplies.
0825 arrived at TMW15 to collect samples and purging the well. We had to collect samples for TMW15 and duplicates for this well DTW15. 0905 we started collecting the samples and completed the collecting at 1035. Earlier in the morning, Luke had TMW14 to collect samples from. The well was frozen. Dave and myself volunteered at 1030 to collect the samples from TMW14. I can't remember which well we went too. It was the last well of the day. We collected the samples and were finished by 1300. Dave and myself reported back to building 5 to check in with Luke and John. We turned in our samples and then went to the fire station to unload our truck to prepare for delivery the ice chest with the samples to fedex. After we delivered the ice chest to fedex, we started on our way back to Albuquerque to the Sandia office. Today was a great day! All team members helped clean-up the fire station and building 5 prior to leaving the worksite at Fort Windgate.

11/6/15
C. O. Waller

10/27/15 FWDA Groundwater Sampling

Facility-Wide October 2015

Weather - cold in AM, 30s, clear and sunny

Personell on site → J. Nance, R. Hobbs, D. Larson,
Connie Vernon, Personell on book J. Nance,
R. Hobbs.

0700 Arrive on site, check in

0730 Safety briefing, pack up materials
for day

0915 Picked up nitro tank

0930 Mob to TMW16, begin purging at
0950

1014 Well purged dry, pack up site

1030 Mob to TMW30 to give generator key to
CH2 Personell

1035 Mob to TMW19, and set up

1040 Begin purging @ approx 3.76 l/m

1152 well dry, pack up site, mob to TMW18

1200 Dump water-IDW water at
evaporation tank

1210 Mob to TMW18, and setup.

Begin purging 1232

1302 Well went dry after reading mets RGH
pack up and mob to TMW37.

1315 Arrive at TMW37 and setup

1338 Start Purging

1402 Finish purging well, dry at 1402,
pack up1425 Mob to evaporation tank to dispose
of IDW water

1435 Return Mob to TMW36

1500 Set up at TMW36

1507 Begin purging

1550 Well purged dry


FWDA G W Sampling Facility Wide

10/27/15

Continued

1600 Dispose of IDW water at evaporation
tank, and return to building 34, put
away equipment for evening.

1640 Leave site for day



Rockel flats


10/27/15

- 10/28/15 FWDA Facility Wide GW Sampling Event October 2015
- 0700 Morning Safety Meeting.
- 0730, Begin to pack up and calibrate for day R.H.
- 0930 Pick up supplies Unable to calibrate DO on meter # to zero. Calibrates to 1.2 mg/L with zero solution. Replaced fluid and membrane on instrument and checked cal. Fluid against another instrument.
- 0950 Picked up ice and bottles from building 5.
 → Personell on site. R. Hobbs, J.Nance, C. Vernon, D. Larson, L Hill, G. Engle
 On Book → R. Hobbs & J. Nance
 Weather: Cold in AM ~ 30s, overcast
- 1020 Arrive at TMW16 and set up
- 1040 Collect TMW16 10/2015
- 1111 Finish collecting sample, packed up, Mob to TMW19
- 1135 Collect Sample at TMW19
- 1200 Finish at TMW19, dispose of IDW water at evaporation tank, and mob to TMW37
- 1241 Collect Sample at TMW37
- 1330 Mob to TMW36
- 1350 Collect TMW36 10/2015
- 1415 Return to building 5 to pack Samples to ship
- 1540 Samples packed → shipment leaves for Fed Ex. Return to building 34 to unload equipment from day.


1620 End of day

Rachel
 10/28/2015

10/29/15 FWDA Facility - wide GW
 c Sampling Event October 2015
 -personell on site: J. Nance R. Hobbs,
 D. Larson, C. Vernon, Gr Engel, L. Hill
 -personnel on book R. Hobbs, J. Nance
 - Weather: Late High 30s in AM, partly cloudy
 0715 Morning safety meeting, calibrate &
 pack up supplies for day
 0834 Mob to TMW18
 0840 Not enough recharge at TMW18
 to sample. Pack up to go to TMW44
 0910 Collect Sample at TMW44
 1010 Collect Sample at TMW39
 1100 Collect Sample at TMW31S
 1205 Collect Sample at TMW30
 1230 ^{fall} Collect Meet with L. Hill to
 determine rest of day's work
 1320 Collect sample at TMW18
 1345 Return to building 5 to pack
 and ship samples
 1530 Printer not working, have
 to hand write COC for shipment
 1545 Samples leave for shipment
 1600 Unload truck for end of day
 1650 dump 1DW water at evaporation
 tank.
 1700 Leave for day


 10/29/15
 Rachel Hobbs

10/30/15 FWDA Facility Wide GW
 c Sampling Event October 2015
 personnel on site: J. Nance, R. Hobbs, L. Hill,
 G. Engel, D. Larson, C. Vernon
 - Weather overcast, raining in AM
 0715 Safety briefing, pack up for day
 0815 Mobilize to MW03
 0830 Begin purging at MW03
 0910 Collect Sample at MW03
 1010 Mob to TMW26
 1115 Collect Sample, Dupe, MS & MSD @
 TMW26
 1220 Mob to TMN27, RQH
 1315 Collect Sample at TMW27
 1330 Return to Building 5 to pack
 Samples for shipping
 1530 Samples leave for delivery, finish
 Cleaning up building for week.
 1600 End of day


 Rachel Hobbs

10/30/15

11/2/15 FT Wingate Facility Wide
GW Sampling Event October 2015
0700 Safety briefing, discuss sampling
for day

Weather: Cold in AM, sunny, clear

Personnel on site: R. Hobbs, J. Nance, C. Vernon, L. Hill, S. Wegesser
Personnel on book: R. Hobbs, J. Nance

0830 Pick up bottles, ice from Building 5 and nitrogen tanks

0850 Arrive at MW20, set up

0930 Control box not working, valve leaking. Try other two, all inoperable.

0945 New control box delivered by FedEx

1002 Begin Purging, USACE Rep J. Reale on site

1030 Collect MW20, DMW20, MW20 MS and MW20 MSD

1400 Return to Building 5 to pack samples to ship

1530 Samples leave for FedEx, clean up, put away equipment.

1600 End of Day

Rachel Hobbs

11/2/15

11/3/15 FT Wingate Facility Wide
GW Sampling Event October 2015
Weather: Breezy, clear, cool in AM - high 30s

Personnel on site: J. Nance, R. Hobbs, C. Vernon, D. Larson, S. Wegesser, L. Hill, On Book - R. Hobbs & J. Nance

0700 - Safety briefing, load up for day

0810 - Mob to SMW01

0910 - Collect Sample at SMW01

1000 - Load up and Mob to TMW34

1040 - Begin Purge @ TMW34

1130 - Collect Sample at TMW34 - Collect DTW34

1215 - Clean up, and go to TMW02 TMW34

1340 - Collect sample at TMW02

1430 - Return to building 5 pack up for shipping

1530 Samples leave for FedEx, Mob to TMW28

1620 Collect Sample at TMW28, return to building 34 and unpack for day

1715 End of day

11/3/15
Rachel Hobbs

11/4/15

FT Wingate, Facility Wide
GW Sampling Event
Oct. 2015

0715 Tailgate safety meeting

0720 Pack up for day

0800 Mob to TMW03, control
box not working - work
on control box to determine
problem.

Weather: Cold, snowy, slushy, sleet
and rain. In 30s.

Personnel on site R. Hobbs, B. Moayyad,
J. Nance, D. Larson, C. Vernon, K. Vernon
S. Wegesser L. Hill.

On Book: R. Hobbs, B. Moayyad,

1000 1000 Sample at TMW03 - Manually
connected well to Nitrogen
to purge and sample since
control box was inoperable

1100 Pack up and mob to TMW39D
Purge and sample using same
method

1200 Sample TMW39D

1220 Pack up, and mob to TMW11.

1250 Begin purging at TMW11

1325 Collect sample at TMW11

1350 Pause sampling due to inclement
weather, then continue sampling

1400 Nitrogen tanks empty. Only able
to get partial sample at TMW11

1415 Return to building 5a to pack
samples to ship for day

1530 Samples to FedEx drop
IDW Water

1600 Pick up J. Nance from USACE office
Look at control box - it is working

1630 End of day

Rachel Hobbs
11/4/15

11/5/15 Ft Wingate Facility Wide GW Sampling Event October 2015
 0715 Tailgate, personnel on site J.Nance, R.Hobbs, C.Vernon, D.Larson, S.Wegesee, L.Hill,
 Weather - Snowy, breezy,
 0815 Pack up for day, mob to MW23
 0910 Begin purging at MW23
 1017 MW23 Purged & Dry, pack up to go to MW24.
 1120 Purging MW24
 1140 Sample MW24, pack up and return to MW23
 1200 Purge MW23 ~100 gallons purged at MW23 at 1300
 1300 Pack up and return to building 5. Conditions muddy on road. Snow melting creating mud. Very hard to drive through
 1330 Pack up materials to sample TMW32
 1350 Begin purging at TMW32
 1500 Collect sample at TMW32, and return to building 5
 1530 Pack up samples to ship
 1540 Samples to Fed Ex
 1630 Take tank to evaporation tank with trash pump to pump off 1Dw water
 1655 End of day.

Rachel Hobbs

11/5/15

11/6/15 Ft Wingate Facility Wide GW Sampling Event October 2015
 Weather - cold in AM - below freezing
 Personnel on site R.Hobbs & J.Nance
 0625 Arrive on site. RH & JN Arrived on site before rest of personnel to get to MW23 while road is still frozen and site is accessible.
 Pack up materials & supplies for day
 0645 Mob to MW23. Road is frozen and possible.
 0725 Begin purging at MW23
 0835 Collect sample at MW23
 0945 Return to Building 5 to pack samples, ship, and clean up. Organize materials and supplies from sampling event
 1430 Samples to Fed Ex. Buildings 5 and 34 cleaned up. Leave site.

Rachel Hobbs
11/6/15

12/11/15

FWDA Additional

Nitrate Sampling Event at TMW28

- 1045 Arrive at FWDA. Check in w/ VSACE. Sign out radio & keys
- 1100 Pack up supplies for nitrate/nitrite sample at TMW-28
- 1130 Arrive at TMW-28 and set up
- 1155 Begin purging 2.75 L/5min
- 1330 Finish purging 3 well volumes → 13 gallons
- 1335 Collect sample for TMW28102015 Nitrate
- 1350 Return to main post, dispose of purge water, and put away supplies
- 1415 Pack sample to ship, fill out COC
- 1445 Return to main trailer to return radio & keys, sign out
- 1500 Return to ABQ → will drop sample at FedEx in ABQ

12/11/15

Rachel Holt