

lura.gonzales

From: Smith, Steve W SWF [Steve.W.Smith@usace.army.mil]
Sent: Thursday, May 13, 2010 7:05 AM
To: Jeffrey.Johnston@CH2M.com
Cc: Diaz, Tammy, NMENV; Patterson, Mark C Mr CIV USA OSA; Esler, Christy L Ms ARMY GUEST USA USACE; Gonzales, Lura Mrs ARMY GUEST USA OSA USA
Subject: Parcel 6 RFI work plan

Jeff,

After reviewing the April 30 version, I found a few things that need correction.

In section 5: page 5-15 states MI samples are to be taken at all locations except the cesspool, however table 5-3 says MI's only at SB01 and SB02. Change this to omit MI's at the surface and do discrettes instead at each boring location except for the cesspool. Include the discrete surface samples in table 5-3.

Section 7: page 7-17, section 7.4.2 says we are still doing MI samples. However refer to comment 21 response. We need to replace all the MI's at the site with discrettes per comment 21. The first bullet (end of page 7-17) leaves out the 6-12" depth on the east side of 542.

Table 7-3, remove the * showing MI samples. Page 7-13 is missing.

Please revise the summary table 4.1 to show all samples and parameters similar to what you did in the Feb 09 version. This would be very useful in the field.

Page 8-14: state the size of the MI area. Use 100'x100'.

Please provide replacement sheets to all on the distribution list for the Apr 30 version. Also supply revised CD's. Include a revised CD with the new CAD/GIS, Word, Excel docs to me. If possible, can you get this done by May 28?

Thanks.

Steven W. Smith F.E.
USACE Fort Wingate Program Manager
817/886-1879