

CURRENT PHOTOGRAPHS

JUNE 2011



Figure 1. Structure 53. Distant View from I 40.



Figure 2. Structure 53. Distant View from Administration Area.



Figure 3. Structure 53. Distant View from Magazine Area.



Figure 4. Structures 53 (left) and 46 (right).



Figure 5. Structure 53. Water Tower.



Figure 6. Structure 46. Water Tank.



Figure 7. Structure 53. Water Tank Detail.



Figure 8. Structure 53. Water Tank Detail.



Figure 9. Structure 6. Gas Station. Front View.



Figure 10. Structure 6. Gas Station. Side View.



Figure 11. Structure 6. Gas Station. Distant View.



Figure 12. Structure 6. Gas Station. Detail of Structural Damage.



Figure 13. Structure 6. Gas Station Canopy Detail.